Oil Field Environmental Incident Summary

Incident: 20160115180108 Date/Time of Notice: 01/15/2016 18:01

Responsible Party: CONTINENTAL RESOURCES, INC. CONTINENTAL RESOURCES, INC.

Well Name: HOROB 1-14H

Field Name: HEBRON Well File #: 18901

Date Incident: 1/15/2016 Time Incident: 13:30 Facility ID Number: WILLIAMS Twp: 155 Rng: 104 Sec: 14 Qtr: County:

Location Description:

Submitted By: NATE STANHOPE Received By:

Contact Person: NATE STANHOPE

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units
Oil	11	Barrels	11	Barrels
Brine	11	Barrels	11	Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

Followup Units

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

All standing fluid was sucked up and impacted soil will be disposed of and replaced with clean fill.

Wastes Disposal Location: Gibson's Environmental Services

Agencies Involved: Jessica Gilke w/ NDIC

Updates

Date: 1/19/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was contained within the diking area. NDIC retains oversight.